



Job Description

Roles and Responsibilities: -

- High Pressure Die Casting Experience Must.
- Shift Handling.
- NG Analysis & reduction.
- Problem Troubleshooting.
- Critical Spare Maintenance.
- Ensure to achieve maximum OEE.

• Willing to work in rotational shifts.

Company Description